



Date — 4-19-93
Location — 910 Kenilworth
Owner — Bob Snyder
Address — 910 Kenilworth
Contractor — Bob Cordes
Address —
Work Discip. — Installation of
backwater valve


P/L

P/L




upstream m/H

R/W



Curb line

Side Walk



D/S Manhole

D/S Manhole

Curb line

C/L —————



Place an X for the manhole applicable.