


1"=20'

th Ave



895

915

Kendworth

925

Installed Cleanout Only

J.A. Hillis  
 3-22-2022  
 Inspected By: A. DabL