


1"=20'  
8-23-2022  
J. Hillis  
Insp. By: A. Dehl



- Replaced a section of 4" pipe that was broke at the 45° Bend turning down by the R/W.
- Ferro's to 4" Cast on both ends