

705 WEST MAUMEE AVENUE  
ILLEGAL DOWNSPOUT INVESTIGATION

67

ALL ILLEGAL CONNECTIONS HAVE BEEN  
CAPPED OR PLUGGED AND ARE IN  
COMPLIANCE AT THIS TIME.  
INSPECTED BY: MARTHA CROSSLAND  
& MARK SPIESS

W. MAUMEE AVE.

12" STM.

10" San.

NOTHING SHOWING  
FRESH LANDSCAPING  
DIRT

705

Tile Above  
Filled w/cont.

c/b

OK

OK

2016



1"=20'

