



--- 6" SDR PVC ---

9-11-91
 Billelling installed c/o
 Jerry Glanz Excav.

BAD

Sewer plugged
 by roots do to
 improper fitting
 of 45° bend to
 top riser.

BAD

