




DYE TEST AND LOCATE. ALL TAPS AND LINES 1689 through 1775

2013







Setup 1	Surveyor Roger Darr	Certificate # U-906-3742	System Owner
Drainage	Survey Customer	Street Oakwood	
P/O #	Date 2013/07/12	Time 8:06	
City	Further location details Napoleon		
Start	1800 OAKWOOD	Rim to invert	Grade to invert
Finish	1722 OAKWOOD	Rim to invert	Grade to invert
Use Sanitary	Direction Downstream	Flow control	Media No 1
Shape Circular	Height 10	Width	ins Preclean J
Material Polyvinyl Chloride	Joint length	Ft Total length	414.1
Lining	Year laid	Year rehabilitated	Weather Saturated
Purpose Routine Assessment	Cat		
Additional info	Structural O&M Miscellaneous Hydraulic		
Location Yard	Constitutional		