


639 PARK STREET



PARK STREET

2015  
 N  
 1" = 20'



WORK PERFORMED BY  
MOCK & BUEHRER BUILDERS

Investigation of illegal sewer connections revealed three (3) illegal connections. All downspouts have been corrected and are in compliance at this time.

SCANNED