


925 PARK STREET



SCANNED



2015
N
1" = 20'

Investigation of illegal sewer connections revealed no illegal connections. All downspouts are in compliance at this time.