

City of Napoleon

BACKFLOW PREVENTION ASSEMBLY TEST RESULTS

Property Address: 612 N. Perry Zip: 43545
 Business Name: Henry Co. Title Dept.
 Contact Person: Dorothy Taylor Title: Maintenance Supervisor
 Phone Number: 592-8977 Date of Test: 2-24-99

DEVICE INFORMATION

Type (circle one) **RP** **DC** **VB** **RPDA** **DCDA**
 Manf/Model: WATB M2 QT Size: 3/4" Serial No.: 91761
 Location of Device: West Wall basement

Type of Test Differential Gauge Sight Tube

Outlet Valve	Reduced Pressure Assembly		Pressure Vacuum Breaker		
	Double Check Valve		Relief Valve	Air Inlet	Check Valve
	1st Check	2nd Check			
Holding <input checked="" type="checkbox"/> Failed <input type="checkbox"/>					
Test Results <u>Pass</u>	DC <u>10</u> psi <u>Apparent</u> RP _____ psi <u>Actual</u> RP _____ psi	DC <u>10</u> psi	Opened at _____ psi Did Not Open <input type="checkbox"/>	Opened at _____ psi Did Not Open <input type="checkbox"/>	Held at _____ psi Leaked <input type="checkbox"/>
Date: <u>2-24-99</u>	Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>
Repairs & Materials					
Test After Repairs	DC _____ psi RP _____ psi	DC _____ psi RP _____ psi	Opened At _____ psi Did Not Open <input type="checkbox"/>	Opened At _____ psi Did Not Open <input type="checkbox"/>	Held At _____ psi Leaked <input type="checkbox"/>
Date:	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>

Tester Signature: Nathan Inge Certification No. 602
 Owner/Representative Signature: Dorothy Taylor