


1"=20'

Sanitary Repair

11-19-18


Tressler Plumbing

Inspected By: A. Deble



1" = 10'

1030



4" - Sch. 40 House to C/O  
6" - SDR 35 C/O to Ferro

1030

HURST  
8"  
W.M.

1102

Tresslers  
11-17-18  
AD

1.5' offset  
cleanout  
to  
45° bend

11'  
76"  
15°  
30" to  
Furnace  
Ex. 4" clay

