

Permit No. _____
 Issued _____
 By _____
 Building Inspector
 Estimated Cost _____

Lot Information:

Sidewalk required in accordance with Ordinance
No. _____

Building Information:

Date 2-1-72 Applicant Signature Ray G. Longaker
Owner - Builder - Agent

Inspection Record:

Comments: Sewer tap on W. P/L 8' Deep 18' Back of Curb 5-2 OKed
85% 12-13 Painting wood work 80% 1-26-83

Certificate of Occupancy Issued _____

Fees	Base	Plus	Total
Construction	504	153	165
Basement			
Detached Garage			
Plumbing	338	94	124
Electrical	34	94	128
Heating	122		122
Air Conditioning			
Water Tap	4	110	114
Sewer Tap		10	10
Temporary Electric	10		10
Total			117

Owner - Builder - Agent

Pink - Engineer

Inspector

SEWER INSPECTION

No. 529

Napoleon, Ohio Date 3-7 1972

Received of Larry Lengacher

Sixty and 00/100 Dollars

Charge for tapping permit to supply sewer service to lot

addition Anthony Wayne 4th.

Street No. 535 Robin

Sewer Size _____ inch

Cost \$ 60.00
pd 2-1-72

Size and Kind of Main Sewer _____

Location of Main Sewer _____

Depth of Main Sewer _____

SEWER INSPECTION

No. 529

Napoleon, Ohio Date 3-7 1972

Received of Larry Lengacher

Sixty and 00/100 Dollars

Charge for tapping permit to supply sewer service to L. C. [unclear]

Addition Anthony Wayne 4th.

Street No. 535 Robin

Sewer Size _____ inch

Cost \$ 60.00
pd 2-1-72

Size and Kind of Main Sewer _____

Location of Main Sewer _____

Depth of Main Sewer _____