

City of Napoleon

BACKFLOW PREVENTION ASSEMBLY TEST RESULTS

Property Address: 1074 A. Scott ZIP: 43545
 Business Name: Superwash

DEVICE INFORMATION

Type (circle one) **RP** DC VB RPDA DCDA

Manf/Model: Watts 909 Size: 2" Serial No. 272092
 Location of Device: mechanical room
 Type of Test: Differential Gauge Sight Tube

Outlet valve holding RP <input checked="" type="checkbox"/> DC <input type="checkbox"/> failed RP <input type="checkbox"/> DC <input type="checkbox"/>	Reduced Pressure Assembly ↓			Pressure Vacuum Breaker	
	Double Check Valve ↓		<u>Relief Valve</u> ↓	Air Inlet	Check Valve
	1st Check	2nd Check			
Test Results <i>Pass</i>	DC _____ psi RP <u>7.0</u> psi	DC _____ psi	opened at <u>4.0</u> psi did not open <input type="checkbox"/>	opened at _____ psi did not open <input type="checkbox"/>	held at _____ psi leaked <input type="checkbox"/>
Date: <i>5-23-01</i>	Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>
Repairs & Materials					
Test After Repairs	DC _____ psi RP _____ psi	DC _____ psi RP _____ psi	opened at _____ psi did not open <input type="checkbox"/>	opened at _____ psi did not open <input type="checkbox"/>	held at _____ psi leaked <input type="checkbox"/>
Date:	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>

Tester Signature: Mark Vetter Certification No. #2335
 Owner/Representative Signature: Larry A. Langer