## City of Napoleon

## BACKFLOW PREVENTION ASSEMBLY TEST RESULTS

Property Address.	1108 1	1.5cott			Zip:43545
Business Name: Pioneer Quick (ube					
Contact Person:	Chris Fin	istermikat		Title:	
Phone Number	599-2800		Date of Test:	2-26-99	
<b>DEVICE INFORMATION</b>					
Type (circle one)	RP	DC	VB	RPDA	DCDA
Type (circle one) RP DC VB RPDA DCDA  Manf/Model: Wats 909 QT RPZ Size: 3/4 Serial No.: 4/2398					
Location of Device: N.E. corner basement					
	Differential Gauge   Sight Tube □				
Outlet	Reduced Pressure Assembly			Pressure Vacuum Breaker	
Valve					
Holding 🗹	Double Check Valve		Relief Valve	Air Inlet	Check Valve
Failed	1st Check	2nd Check	Ų ÷		
Test	DC psi	DC psi	Opened at	Opened at	Held at
Test Results Pass				psi	psi
	Apparent				
outlet value,	RP 7.0 psi				
needs replaced	Actual		Did Not	Did Not	Leaked
	RP <u>7.2</u> psi	7.0	Open	Open	
Date: 26-99	Pass 🗵	Pass 🗷	Pass 🗷	Pass	Pass $\square$
ar de	Failed	Failed	Failed	Failed	Failed
Repairs &					
Materials					
		·			
•			Opened At	Opened At	Held At
Test After	DC psi	DC psi	psi	psi	psi
Repairs			Did Not	Did Not	
	RP psi	RP psi	Open	Open	Leaked
Date:	Pass	Pass	Pass	Pass	Pass
	Failed	Failed	Failed	Failed	Failed
Tester Signature / Athan Duh Certification No. 602					
Owner/Representative Signature:					