

City of Napoleon

BACKFLOW PREVENTION ASSEMBLY TEST RESULTS

Property Address: 1108 NORTH SCOTT ZIP: 43545
 Business Name: PIONEER QUICK LUBE

DEVICE INFORMATION

Type (circle one) RP **DC** VB RPDA DCDA

Manf/Model: AMES 3000 SS Size: 2 1/2 Serial No. 9AL0022

Location of Device: BASEMENT

Type of Test: Differential Gauge Sight Tube

Outlet valve holding RP <input type="checkbox"/> DC <input checked="" type="checkbox"/> failed RP <input type="checkbox"/> DC <input type="checkbox"/>	Reduced Pressure Assembly ↓		Relief Valve ↓	Pressure Vacuum Breaker	
	Double Check Valve ↓			Air Inlet	Check Valve
	1st Check	2nd Check			
Test Results <i>Pass</i>	DC <u>4</u> psi	DC <u>3.2</u> psi	opened at _____ psi	opened at _____ psi	held at _____ psi
	RP _____ psi		did not open <input type="checkbox"/>	did not open <input type="checkbox"/>	leaked <input type="checkbox"/>
Date: <u>5-7-02</u>	Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>
Repairs & Materials					
Test After Repairs	DC _____ psi	DC _____ psi	opened at _____ psi	opened at _____ psi	held at _____ psi
	RP _____ psi	RP _____ psi	did not open <input type="checkbox"/>	did not open <input type="checkbox"/>	leaked <input type="checkbox"/>
Date:	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>

Tester Signature: *Donna Legut* Certification No. 2539
 Owner/Representative Signature: *Debra Jones*