

City of Napoleon

BACKFLOW PREVENTION ASSEMBLY TEST RESULTS

Property Address: 1108 SCOTT ST. ZIP: 49545
 Business Name: PIONEER QUICK LUBE

DEVICE INFORMATION

Type (circle one) RP DC VB RPDA DCDA

Manf/Model: WATTS 007 M2 QT Size: 3/4 Serial No. 60935

Location of Device: _____

Type of Test: Differential Gauge Sight Tube

| Outlet valve holding RP <input type="checkbox"/> DC <input checked="" type="checkbox"/> failed RP <input type="checkbox"/> DC <input type="checkbox"/> | Reduced Pressure Assembly ↓ | | | Pressure Vacuum Breaker | |
|--|---|---|--|--|--|
| | Double Check Valve ↓ | | Relief Valve ↓ | Air Inlet | Check Valve |
| | 1st Check | 2nd Check | | | |
| Test Results | DC <u>1.1</u> psi RP _____ psi | DC <u>1.5</u> psi | opened at _____ psi did not open <input type="checkbox"/> | opened at _____ psi did not open <input type="checkbox"/> | held at _____ psi leaked <input type="checkbox"/> |
| Date: <u>3-26-03</u> | Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/> | Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/> | Pass <input type="checkbox"/> Failed <input type="checkbox"/> | Pass <input type="checkbox"/> Failed <input type="checkbox"/> | Pass <input type="checkbox"/> Failed <input type="checkbox"/> |
| Repairs & Materials | | | | | |
| Test After Repairs | DC _____ psi RP _____ psi | DC _____ psi RP _____ psi | opened at _____ psi did not open <input type="checkbox"/> | opened at _____ psi did not open <input type="checkbox"/> | held at _____ psi leaked <input type="checkbox"/> |
| Date: | Pass <input type="checkbox"/> Failed <input type="checkbox"/> | Pass <input type="checkbox"/> Failed <input type="checkbox"/> | Pass <input type="checkbox"/> Failed <input type="checkbox"/> | Pass <input type="checkbox"/> Failed <input type="checkbox"/> | Pass <input type="checkbox"/> Failed <input type="checkbox"/> |

Tester Signature: [Signature] Certification No. 2539
 Owner/Representative Signature: [Signature]