

City of Napoleon

BACKFLOW PREVENTION ASSEMBLY TEST RESULTS

Property Address: 1109 N. Scott ZIP: 43545
 Business Name: Pioneer Quick Lube

DEVICE INFORMATION

Type (circle one) **RP** **DC** **VB** **RPDA** **DCDA**
 Manf/Model: Ames 3000 SS Size: 2 1/2" Serial No. 3AL0022
 Location of Device: N.E. Corner basement
 Type of Test: Differential Gauge Sight Tube

Outlet valve holding RP <input type="checkbox"/> DC <input checked="" type="checkbox"/> failed RP <input type="checkbox"/> DC <input type="checkbox"/>	Reduced Pressure Assembly ↓			Pressure Vacuum Breaker	
	Double Check Valve ↓		Relief Valve ↓	Air Inlet	Check Valve
	1st Check	2nd Check			
Test Results <i>Pass</i>	DC <u>3.6</u> psi	DC <u>2.5</u> psi	opened at _____ psi	opened at _____ psi	held at _____ psi
	RP _____ psi		did not open <input type="checkbox"/>	did not open <input type="checkbox"/>	leaked <input type="checkbox"/>
Date: <i>3-31-84</i>	Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>
Repairs & Materials	<i>1109 N. Scott St</i>				
Test After Repairs	DC _____ psi	DC _____ psi	opened at _____ psi	opened at _____ psi	held at _____ psi
	RP _____ psi	RP _____ psi	did not open <input type="checkbox"/>	did not open <input type="checkbox"/>	leaked <input type="checkbox"/>
Date:	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>

Tester Signature: *Douglas J. Suter* Certification No. 2539
 Owner/Representative Signature: *Lynn Dennis Mgr.*