

CITY OF NAPOLEON

BUILDING CONSTRUCTION PERMIT

Owner Name Arroyo Plastics  
Address 441 North Scott  
Builder Name Mel Lanzetta  
Address N Scott St Tel. \_\_\_\_\_

Permit No. \_\_\_\_\_  
Issued 7-14-72  
By \_\_\_\_\_  
Building Inspector  
Estimated Cost 12,462

Lot Information:

Street No. 1409 N. Scott St  
Lot \_\_\_\_\_ Subdivision \_\_\_\_\_  
Lot Dimensions \_\_\_\_\_ Lot Area \_\_\_\_\_ Sq. Ft.  
Yard Set Back: Front \_\_\_\_\_ Rear \_\_\_\_\_  
Side \_\_\_\_\_ Side \_\_\_\_\_

Sidewalk required in accordance with Ordinance  
No. \_\_\_\_\_

Building Information:

Residence \_\_\_\_\_ Commercial \_\_\_\_\_ Industrial \_\_\_\_\_  
Single \_\_\_\_\_ Double \_\_\_\_\_ Multiple \_\_\_\_\_ New Construction \_\_\_\_\_ Addition \_\_\_\_\_ Remodel \_\_\_\_\_  
Size: Length 34 Width 20 No. of Stories \_\_\_\_\_  
Floor Area: 1st Floor 612 SF 2nd Floor \_\_\_\_\_ 3rd Floor \_\_\_\_\_ Basement \_\_\_\_\_  
Unfinished Attic \_\_\_\_\_ Garage \_\_\_\_\_  
Foundation: Piers \_\_\_\_\_ Full Basement \_\_\_\_\_ Part Basement \_\_\_\_\_  
Concrete \_\_\_\_\_ Block \_\_\_\_\_  
Walls: Frame \_\_\_\_\_ Block \_\_\_\_\_ Brick \_\_\_\_\_ Other \_\_\_\_\_  
Electrical Outlets: 120v \_\_\_\_\_ 240v \_\_\_\_\_  
Plumbing: Fixtures \_\_\_\_\_ Traps \_\_\_\_\_ Vents \_\_\_\_\_ Heating \_\_\_\_\_ Air Conditioning \_\_\_\_\_  
Additional Information: \_\_\_\_\_

Fees	Base	Plus	Total
Construction	<u>11,200</u>	<u>1,262</u>	<u>12,462</u>
Basement	_____	_____	_____
Detached Garage	_____	_____	_____
Plumbing	_____	_____	_____
Electrical	_____	_____	_____
Heating	_____	_____	_____
Air Conditioning	_____	_____	_____
Water Tap	_____	_____	_____
Sewer Tap	_____	_____	_____
Temporary Electric	_____	_____	_____
Total	_____	_____	<u>12,462</u>

Date 7-14-72 Applicant Signature Richard L. Osterman  
Owner - Builder - Agent

Inspection Record:

Work Started \_\_\_\_\_ Foundations \_\_\_\_\_ Plumbing, Heating \_\_\_\_\_  
Set Back, Side Lines \_\_\_\_\_ Plumbing (Rough In) 8-1-72 And Air Conditioning \_\_\_\_\_  
Excavation 7-17-72 Erecting Frame \_\_\_\_\_ Roof \_\_\_\_\_  
Footing 7-18-72 Electrical Work \_\_\_\_\_  
Comments: 6.5 cu yds CONC Factor  
100% 11-28

Certificate of Occupancy Issued \_\_\_\_\_  
Pink - Engineer Inspector Carl M. Long