## City of Napoleon

## BACKFLOW PREVENTION ASSEMBLY TEST RESULTS

Property Address:	1413 11.	Scott		No. of the second	Zip: 43545
Business Name: Hyston's Launders + Cleaners					
Contact Person:	I'm HUST	00		Title: Owner	•
Phone Number:	592-294	1	Date of Test: 3	-6-00	
DEVICE INFORMATION					
Type (circle one)	RP	DC	VB	RPDA	DCDA
Manf/Model: 009 M2 QT Watts Size: 1" Serial No.: 74078					
Location of Device: N.E. Corner Mechanical room					
Type of Test:	Differential Gauge	8	Sight Tube		
Outlet	Reduced Pressure Assembly			Pressure Vacuum Breaker	
Valve					
Holding 🔀	Double Check Valve		Relief Valve	Air Inlet	Check Valve
Failed	1st Check	2nd Check	Į.		
Test 5	DCpsi	DC psi	Opened at	Opened at	Held at
Results Q55			2.8 psi	psi	psi
	Apparent				· · · · · · · · · · · · · · · · · · ·
	RP 8.6 psi				
	Actual		Did Not	Did Not	Leaked
00	RP 3 2 psi	2	Open	Open	
Date: 16	Pass 💹	Pass 🔊	Pass 🛎	Pass	Pass 🗆
3	Failed	Failed	Failed	Failed	Failed
4.3					
Repairs &					
Materials					
			*		
			Opened At	Opened At	Held At
Test After	DC psi	DC psi	psi	psi	psi
Repairs			Did Not	Did Not	P51
	RP psi	RP psi	Open	Open	Leaked
		po.		open 🗀	Douned _
Date:	Pass	Pass	Pass 🗆	Pass 🗆	Pass 🗆
Date.					
	ranca L	Failed	Failed	Failed	Failed
Tester Signature: Brian Jull Certification No. 611					
Owner/Representative Signature: Jim Huston					