City of Napoleon

BACKFLOW PREVENTION ASSEMBLY TEST RESULTS

Property Address.	1413 n.	Scott il	Papoleon De	hio	Zip: 43545
Business Name: Huston's Launders + Cleaners					
	Tim Huston				
	592-294/ Date of Test: 7-/6-98				
DEVICE INFORMATION					
Type (circle one)	RP	DC	VB	RPDA	DCDA
Manf/Model:	009 QT		Size:/ "	Serial No.: 2693	55
Location of Device: Northwall behind Compressor					
Type of Test. Differential Gauge 🖾 Sight Tube 🗆					
Outlet	Reduced Pressure	Assembly		Pressure Vacuum Breaker	
Valve					
Holding	Double Check Valve		Relief Valve	Air Inlet	Check Valve
Failed	1st Check	2nd Check	U		
				/	
Test Results Fail	DC psi	DC psi		Opened at	Held at
Results [ail			psi	psi	psi
	Apparent				
	RPpsi				
	Actual		Did Not	Did Not	Leaked
	RP 8.4 psi		Open	Open	
Date:	Pass 🗏	Pass	Pass	Pass	Pass \square
7-16-98	Failed	Failed M	Failed	Failed	Failed
Repairs & Materials					
			Opened At	Opened At	Held At
Test After	DC psi	DC psi	psi	psi	psi
Repairs			Did Not	Did Not	
	RP psi	RP psi	Open	Open	Leaked
Date:	Pass 🗆	Pass	Pass	Pass 🗆	Pass
	Failed	Failed		Failed	Failed
Tester Signature: Certification No. 611 Owner/Representative Signature:					