

City of Napoleon

BACKFLOW PREVENTION ASSEMBLY TEST RESULTS

Property Address: 1416 N. Scott Zip: 43545
 Business Name: Henry Co. Bank
 Contact Person: Roger Murry Title: _____
 Phone Number: 599-9015 Date of Test: 4-23-99

DEVICE INFORMATION

Type (circle one) **RP** **(DC)** **VB** **RPDA** **DCDA**
 Manf/Model: Watts 007 Size: 3/4" Serial No.: 173422
 Location of Device: S.W. Corner basement

Type of Test: Differential Gauge Sight Tube

Outlet Valve	Reduced Pressure Assembly		Pressure Vacuum Breaker		
	Double Check Valve		Relief Valve	Air Inlet	Check Valve
	1st Check	2nd Check			
Holding <input checked="" type="checkbox"/> Failed <input type="checkbox"/>					
Test Results: <u>Pass</u> Date: <u>4-23-99</u>	DC <u>10</u> psi <u>Apparent</u> RP _____ psi <u>Actual</u> RP _____ psi	DC <u>10</u> psi	Opened at _____ psi Did Not Open <input type="checkbox"/>	Opened at _____ psi Did Not Open <input type="checkbox"/>	Held at _____ psi Leaked <input type="checkbox"/>
	Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>
Repairs & Materials					
Test After Repairs Date:	DC _____ psi RP _____ psi	DC _____ psi RP _____ psi	Opened At _____ psi Did Not Open <input type="checkbox"/>	Opened At _____ psi Did Not Open <input type="checkbox"/>	Held At _____ psi Leaked <input type="checkbox"/>
	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>

Tester Signature: Robert Mielman Certification No. 3016
 Owner/Representative Signature: Thomas J. Stanford