

# City of Napoleon

## BACKFLOW PREVENTION ASSEMBLY TEST RESULTS

Property Address: 1441 Scott Napoleon Ohio Zip: 43545  
 Business Name: Fritz's Tire Rack  
 Contact Person: Fritz Freytag Title: owner  
 Phone Number: 419 599 8473 Date of Test: 8-11-99

### DEVICE INFORMATION

Type (circle one) RP DC VB RPDA DCDA  
 Manf/Model: Wilkins / 950XL Size: 3/4 Serial No.: 398713  
 Location of Device: Mech Room  
 Type of Test: Differential Gauge  Sight Tube

Outlet Valve	Reduced Pressure Assembly			Pressure Vacuum Breaker	
	Double Check Valve		Relief Valve	Air Inlet	Check Valve
	1st Check	2nd Check			
Holding <input checked="" type="checkbox"/> Failed <input type="checkbox"/>					
Test Results: <u>Pass</u>  Date: <u>8-11-99</u>	DC <u>10</u> psi  Apparent RP _____ psi Actual RP _____ psi	DC <u>10</u> psi	Opened at _____ psi  Did Not Open <input type="checkbox"/>	Opened at _____ psi  Did Not Open <input type="checkbox"/>	Held at _____ psi  Leaked <input type="checkbox"/>
	Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>
Repairs & Materials					
Test After Repairs  Date:	DC _____ psi  RP _____ psi	DC _____ psi  RP _____ psi	Opened At _____ psi  Did Not Open <input type="checkbox"/>	Opened At _____ psi  Did Not Open <input type="checkbox"/>	Held At _____ psi  Leaked <input type="checkbox"/>
	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>

Tester Signature: Brian Feil Certification No. 611  
 Owner/Representative Signature: Fredrick Freytag