

# City of Napoleon

## BACKFLOW PREVENTION ASSEMBLY TEST RESULTS

Property Address: 1855 N. Scott ZIP: 43545  
 Business Name: Heritage town

### DEVICE INFORMATION

Type (circle one) **RP**      DC      VB      RPDA      DCDA

Manf/Model: Watts 009 M3QT      Size: 3/4      Serial No. 73374

Location of Device: S.W. corner of bldg.

Type of Test:    Differential Gauge       Sight Tube

Outlet valve holding RP <input checked="" type="checkbox"/> DC <input type="checkbox"/> failed RP <input type="checkbox"/> DC <input type="checkbox"/>	Reduced Pressure Assembly ↓			Pressure Vacuum Breaker	
	Double Check Valve ↓		Relief Valve ↓	Air Inlet	Check Valve
	1st Check	2nd Check			
Test Results <i>Pass</i>	DC _____ psi	DC _____ psi	opened at <u>5</u> psi	opened at _____ psi	held at _____ psi
	RP <u>9.5</u> psi		did not open <input type="checkbox"/>	did not open <input type="checkbox"/>	leaked <input type="checkbox"/>
Date: <i>3-11-02</i>	Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>
Repairs & Materials					
Test After Repairs	DC _____ psi	DC _____ psi	opened at _____ psi	opened at _____ psi	held at _____ psi
	RP _____ psi	RP _____ psi	did not open <input type="checkbox"/>	did not open <input type="checkbox"/>	leaked <input type="checkbox"/>
Date:	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>

Tester Signature: [Signature]      Certification No. 432  
 Owner/Representative Signature: [Signature]