

# City of Napoleon

## BACKFLOW PREVENTION ASSEMBLY TEST RESULTS

Property Address: 1865 N. Scott ZIP: 43545  
 Business Name: Heritage Town

### DEVICE INFORMATION

Type (circle one)    RP    **DC**    VB    RPDA    DCDA

Manf/Model: AMES 3000 55F    Size: 4"    Serial No. 2000250901  
 Location of Device: N.W. Corner of bldg:  
 Type of Test:    Differential Gauge     Sight Tube     Fireline

Outlet valve holding RP <input type="checkbox"/> DC <input checked="" type="checkbox"/> failed RP <input type="checkbox"/> DC <input type="checkbox"/>	Reduced Pressure Assembly ↓			Pressure Vacuum Breaker	
	Double Check Valve ↓		Relief Valve ↓	Air Inlet	Check Valve
	1st Check	2nd Check			
Test Results <u>Pass</u>	DC <u>2.75</u> psi RP _____ psi	DC <u>3</u> psi	opened at _____ psi  did not open <input type="checkbox"/>	opened at _____ psi  did not open <input type="checkbox"/>	held at _____ psi  leaked <input type="checkbox"/>
Date: <u>3-11-02</u>	Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>
Repairs & Materials					
Test After Repairs	DC _____ psi RP _____ psi	DC _____ psi RP _____ psi	opened at _____ psi did not open <input type="checkbox"/>	opened at _____ psi did not open <input type="checkbox"/>	held at _____ psi leaked <input type="checkbox"/>
Date:	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>

Tester Signature: [Signature]    Certification No. 432  
 Owner/Representative Signature: [Signature]