## City of Napoleon

## BACKFLOW PREVENTION ASSEMBLY TEST RESULTS

Property Address.	2240 N	Scott S.	Napoleon	04	Zip: 43545	
Business Name Pizza Hut						
Contact Person:	Ann Flory	4		Title: C-M		
Phone Number	599.901	0	Date of Test: 7	.15-99		
DEVICE INFORMATION						
Type (circle one)	(RP)	DC	VB	RPDA	DCDA	
Manf/Model: W	Ikias	975XL	Size: 1/2	Serial No.: 29	9309	
Location of Device: BackRoom						
Type of Test.	Differential Gauge Sight Tube					
Outlet	Reduced Pressure Assembly			Pressure Vacuum Breaker		
Valve						
Holding 🗲	Double Check Valve		Relief Valve	Air Inlet	Check Valve	
Failed	1st Check	2nd Check	To De Contraction			
Test	DC 8,4 psi	DC 7.2 psi	Opened at	Opened at	Held at	
Results		(97)	3,4 psi	psi	psi	
	Apparent		/			
	RP 8.6 psi					
A 40 - 20 - 30	Actual		Did Not	Did Not	Leaked	
	RP 7.2 psi		Open	Open		
Date:	Pass 🖆	Pass 🖃	Pass 🗷	Pass 🗆	Pass 🗆	
	Failed	Failed	Failed	Failed	Failed	
					11	
Repairs &						
Materials						
\			Opened At	Opened At	Held At	
Test After	DCpsi	DCpsi	psi	psi	psi	
Repairs			Did Not	Did Not		
	RP psi	RP psi	Open	Open	Leaked	
Date:	Pass	Pass	Pass	Pass	Pass	
	Failed	Failed	Failed	Failed	Failed	
<i>i</i> 11						
Tester Signature:	Brian	Jest		Certification No.	611	
Owner/Representative Signature:						
- Corregoration Corp.						