

City of Napoleon

BACKFLOW PREVENTION ASSEMBLY TEST RESULTS

Property Address: 2250 N. Scott Zip: 43545

Business Name: Amvets

Contact Person: Art Bearditt Title: Trustee

Phone Number: 592-4868 Date of Test: 3-23-01

Detector Fireline

DEVICE INFORMATION

Type (circle one) RP **DC** VB RPDA DCDA

Manf/Model: Watts 007 m2 Size: 3/4 Serial No.: 95018

Location of Device: Plumbing closet

Type of Test: Differential Gauge Sight Tube

Outlet Valve	Reduced Pressure Assembly			Pressure Vacuum Breaker	
	Double Check Valve		Relief Valve	Air Inlet	Check Valve
	1st Check	2nd Check			
Holding <input checked="" type="checkbox"/> Failed <input type="checkbox"/>					
Test Results: <u>Pass</u> Date: <u>3-23-01</u>	DC <u>10</u> psi <u>Apparent</u> RP _____ psi <u>Actual</u> RP _____ psi Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	DC <u>10</u> psi Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Opened at _____ psi Did Not Open <input type="checkbox"/> Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Opened at _____ psi Did Not Open <input type="checkbox"/> Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Held at _____ psi Leaked <input type="checkbox"/> Pass <input type="checkbox"/> Failed <input type="checkbox"/>
Repairs & Materials					
Test After Repairs Date:	DC _____ psi RP _____ psi Pass <input type="checkbox"/> Failed <input type="checkbox"/>	DC _____ psi RP _____ psi Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Opened At _____ psi Did Not Open <input type="checkbox"/> Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Opened At _____ psi Did Not Open <input type="checkbox"/> Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Held At _____ psi Leaked <input type="checkbox"/> Pass <input type="checkbox"/> Failed <input type="checkbox"/>

Tester Signature: Dan Zerk Certification No. 2539

Owner/Representative Signature: Laura S. M... 66