City of Napoleon

BACKFLOW PREVENTION ASSEMBLY TEST RESULTS

Property Address:	2255 N.S.	off			Zip: 43545
Business Name:	ss Name: Ftm Bank				
Contact Person:	steve Jack	4500		Title: Branch manager	
Phone Number	592-2077		Date of Test: 7-27-99		
DEVICE INFORMATION					
Type (circle one)	RP	(DC)	VB	RPDA	DCDA
Manf/Model: Wa	tts cor		Size: 1	Serial No.: 214	88
Location of Device: in furnace room					
	Differential Gauge Sight Tube				
	Reduced Pressure A			Pressure Vacuum Breaker	
Valve					
Holding X	Double Check Valve		Relief Valve	Air Inlet	Check Valve
Failed	1st Check	2nd Check			
Test Pass	DC 9,6 psi	DC 10 psi	Opened at	Opened at	Held at
Results			psi	psi	psi
	Apparent				
	RP psi	**			
	Actual	Tes.	Did Not	Did Not	Leaked
- 99	RP psi		Open	Open	
Date: 7-27-99	Pass 🖾	Pass 🗷	Pass	Pass 🗆	Pass
	Failed	Failed	Failed	Failed	Failed
Repairs &					
Materials		9 790			
	,	•	Opened At	Opened At	Held At
Test After	DCpsi	DC psi	psi	psi	psi
Repairs	•		Did Not	Did Not	
repairs	RP psi	RP psi	Open	Open	Leaked
Date:	Pass	Pass	Pass	Pass 🗆	Pass
Bute.	Failed	Failed	Failed	Failed	Failed
Tester Signature:	1 MADE	(A)		Certification No.	7757
Owner/Representative Signature: Mile Schriffe					
Owner/Representative Signature.					