

City of Napoleon

BACKFLOW PREVENTION ASSEMBLY TEST RESULTS

Property Address: 2269 Scott St Napoleon OH Zip: 43545
 Business Name: Midwest Wood Trim
 Contact Person: Gene Short Title: Pres
 Phone Number: 419-592-3384 Date of Test: 7-15-99

DEVICE INFORMATION

Type (circle one) **RP** DC VB RPDA DCDA
 Manf/Model: Watts 009 M20T Size: 1" Serial No.: 52159
 Location of Device: Mech in office

Type of Test: Differential Gauge Sight Tube

Outlet Valve	Reduced Pressure Assembly			Pressure Vacuum Breaker	
	Double Check Valve		Relief Valve	Air Inlet	Check Valve
	1st Check	2nd Check			
Holding <input checked="" type="checkbox"/> Failed <input type="checkbox"/>					
Test Results	DC <u>6.6</u> psi	DC <u>6.2</u> psi	Opened at <u>3</u> psi	Opened at _____ psi	Held at _____ psi
	<u>Apparent</u> RP <u>6.8</u> psi		Did Not Open <input type="checkbox"/>	Did Not Open <input type="checkbox"/>	Leaked <input type="checkbox"/>
	<u>Actual</u> RP <u>6.2</u> psi				
Date: <u>7-15-99</u>	Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>
Repairs & Materials					
Test After Repairs	DC _____ psi	DC _____ psi	Opened At _____ psi	Opened At _____ psi	Held At _____ psi
	RP _____ psi	RP _____ psi	Did Not Open <input type="checkbox"/>	Did Not Open <input type="checkbox"/>	Leaked <input type="checkbox"/>
Date:	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>

Tester Signature: Brian Fejell Certification No. 611
 Owner/Representative Signature: Gene Short