City of Napoleon

BACKFLOW PREVENTION ASSEMBLY TEST RESULTS

Type (circle	one) RP	DEVICE IN	NFORMATIO VB		A DCDA
		9 QT	Size: /	Serial No.	549441
Location of I	Device: West	wall of t	asement	by water	meter
Type of Test	: Differential	Gauge 🔼	Sight Tube		
Outlet	Reduced Pressure			Pressure Vacuum Breaker	
valve	Assembly ↓				
holding	Double Check Valve		Relief	Air Inlet	Check Valve
RPM DC	U Time to the second of the s		Valve		
failed	1st Check	2nd Check	Ŭ U		
RP DC					
Test	DCpsi	DCpsi	opened at	opened at	held at
Results			3.2 psi	psi	psi
Pass	RP 9, 2 psi				
	ps.		did not	did not	leaked
			open 🗆	open 🗆	
Date:	Pass 🗷	Pass 🗵	Pass D	Pass	Pass
6-19-03	Failed		Failed	Failed	Failed
Repairs &	Relief V	alue nee	ds Drain	pipe ins	talled ASAP
Materials					
				•	
				•	
Test After	DC psi	DC psi	opened at psi	opened at psi	held at psi
Repairs	DCpsi	psi	did not	did not	
	RPpsi	RPpsi	open 🗆	open 🗆	leaked
Date:	Pass	Pass	Pass	Pass	Pass
	Failed	Failed	Failed	Failed	Failed
-		11	<u></u>		