

P E R M I T

CITY OF NAPOLEON  
255 W. RIVERVIEW AVE  
NAPOLEON, OHIO 43545

DIVISION OF BUILDING & ZONING  
PH (419) 592-4010  
FAX (419) 599-8393

PERMIT NO: 1551                      DATE ISSUED: 03-28-03                      ISSUED BY: BND  
JOB LOCATION: 1023 N SHEFFIELD AVE                      EST. COST: 2800.00

LOT #:                                      SUBDIVISION NAME:  
  
OWNER: SHONDELL, HASSEL                      AGENT: VONDEYLEN PLBG & HTG  
ADDRESS: 1023 N SHEFFIELD AVE                      ADDRESS: 116 E CLINTON ST  
CS2: NAPOLEON, OH 43545                      CS2: NAPOLEON, OH 43545  
PHONE:                                      PHONE: 419-592-4756

USE TYPE - RESIDENTIAL:                      OTHER:

ZONING INFORMATION

DIST:                      LOT DIM:                      AREA:                      FYRD:                      SYRD:                      RYRD:  
MAX HT:                      # PKG SPACES:                      # LOADING SP:                      MAX LOT COV:

BOARD OF ZONING APPEALS:

WORK TYPE - NEW:                      REPLMNT:                      ADD'N:                      ALTER:                      REMODEL:

WORK INFORMATION

SIZE - LGTH:                      WIDTH:                      STORIES:                      LIVING AREA SF:  
GARAGE AREA SF:                      HEIGHT:                      BLDG VOL DEMO PERMIT:


WORK DESCRIPTION  
FURNACE REPLACEMENT

FEE DESCRIPTION	PAID DATE	FEE AMOUNT DUE
MECHANICAL PERMIT		5.00

TOTAL FEES DUE                      5.00

4-3-03  
-----  
DATE

*Randall P. Fisher*  
-----  
APPLICANT SIGNATURE



CITY OF NAPOLEON INSPECTION FORM

PERMIT #: 1551

DATE ISSUED: 03-28-2003

JOB LOCATION: 1023 N SHEFFIELD AVE

OWNER: SHONDELL, HASSEL

OWNER PHONE:

CONTRACTOR: VONDEYLEN PLBG & HTG

CONTRACTOR PHONE: 419-592-4756

WORK DESCRIPTION: FURNACE REPLACEMENT

PLUMBING: UNDGR \_\_\_\_\_ RGHIN \_\_\_\_\_ FINAL \_\_\_\_\_

SEWER INSP \_\_\_\_\_

MECHANICAL: UNDGR \_\_\_\_\_ RGHIN \_\_\_\_\_ FINAL \_\_\_\_\_

FURNACE REPLC 3-28 AIR COND \_\_\_\_\_

ELECTRICAL: UNDGR \_\_\_\_\_ RGHIN \_\_\_\_\_ FINAL \_\_\_\_\_

SERV UPGR \_\_\_\_\_

BUILDING: SITE \_\_\_\_\_ FTG \_\_\_\_\_ FNDT \_\_\_\_\_

STRUC \_\_\_\_\_ ROOF \_\_\_\_\_ EXT \_\_\_\_\_

VENT \_\_\_\_\_ ACCES \_\_\_\_\_ EGRS \_\_\_\_\_

SMKDT \_\_\_\_\_ FINAL \_\_\_\_\_

ISSUE TEMP OCCUP \_\_\_\_\_ ISSUE OCCUP \_\_\_\_\_

STRG SHED: SITE \_\_\_\_\_ FINAL \_\_\_\_\_

SIGN: FTG \_\_\_\_\_ FINAL \_\_\_\_\_

FENCE: SITE \_\_\_\_\_ FINAL \_\_\_\_\_

APPROVED

MISC INSP: \_\_\_\_\_

NOTES: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

INSPECTOR INITIALS: MSD