

Investigation of illegal sewer connections revealed two (2) illegal connections. All downspouts have been corrected and are in compliance at this time.

CAPPED & CEMENTED  
BELOW GRADE

SCANNED  
1" = 20'

1472

8" San.



TAYLOR DRIVE