PERMIT

CITY OF NAPOLEON 255 W. RIVERVIEW AVE NAPOLEON, OHIO 43545

DIVISION OF BUILDING & ZONING PH (419) 592-4010 FAX (419) 599-8393

PERMIT NO: 1824 DATE ISSUED: 08-20-03 ISSUED BY: TJK

JOB LOCATION: 727 THIRD ST

EST. COST: 4700.00

LOT #:

SUBDIVISION NAME:

OWNER: WEAVER, MIKE

ADDRESS: 727 THIRD ST

CSZ: NAPOLEON, OH 43545

PHONE: 419-599-6456

AGENT: VONDEYLEN PLBG & HTG

ADDRESS: 116 E CLINTON ST

CSZ: NAPOLEON, OH 43545

PHONE: 419-592-4756

USE TYPE - RESIDENTIAL:

OTHER:

ZONING INFORMATION

DIST: LOT DIM: AREA: FYRD: SYRD: RYRD: MAX HT: # PKG SPACES: # LOADING SP: MAX LOT COV:

BOARD OF ZONING APPEALS:

WORK TYPE - NEW: REPLMNT: ADD'N: ALTER: REMODEL:

WORK INFORMATION

SIZE - LGTH: WIDTH: STORIES: LIVING AREA SF: GARAGE AREA SF: HEIGHT: BLDG VOL DEMO PERMIT:

WORK DESCRIPTION FURNACE REPLACEMENT

FEE DESCRIPTION PAID DATE

FEE AMOUNT DUE

5.00

MECHANICAL PERMIT

TOTAL FEES DUE 5.00

DATE

8-20-03

APPLICANT SIGNATURE

AUG Z U 2003 CITY OF NAPOLEON

CITY OF NAPOLEON GENERAL PERMIT APPLICATION THIS APPLICATION IS FOR RESIDENTIAL CONSTRUCTION INCLUDING BUILDING, ELECTRICAL, PLUMBING, MECHANICAL, DEMILITIONS, REMODELING

Date 8-20-03	Job Location		
Owner Michael U	NELVET	Phone 599-64.	56
Owner Address 727 7	Lird Street	City Naplem	Zip43545
Contractor Von Dayler	Plbg ttts,	Phone	92-4756
Description of work to be pro-	eformed Replace	Ferrace +1	1/-
Estimated cost of work to be	4000	2.5	
Delow 1	Please check the work t	hat you will be doing!!	
A/C Add On			_Remodeling
Boiler Replacen	nent	-	_Roofing
Curbing			Sewer Repairs
Decks			Sidewalk
Driveway			Siding
Electrical Service Upgrade			Sign
Electrical New		—	Storage Shed
Fence			Street Bond
Foundation			Swimming Pool
Furnace Replacement		N-	Temp Electric
Furnace New			Water Tap
Lawn Meter			Windows
Plumbing	.mrl		Zoning
Others	Permit Nu	mber	

CITY OF NAPOLEON INSPECTION FORM

PERMIT #: 1824
DATE ISSUED: 08-20-2003
JOB LOCATION: 727 THIRD ST
OWNER: WEAVER, MIKE
OWNER PHONE: 419-599-6456
CONTRACTOR: VONDEYLEN PLBG & HTG
CONTRACTOR PHONE: 419-592-4756
WORK DESCRIPTION: FURNACE REPLACEMENT
PLUMBING: UNDGR RGHIN FINAL
SEWER INSP
MECHANICAL: UNDGR RGHIN FINAL
FURNACE REPLC 8-21-07 AIR COND
ELECTRICAL: UNDGR RGHIN FINAL
SERV UPGR
BUILDING: SITE FTG FNDT
STRUC ROOF EXT
VENT ACCES EGRS
SMKDT FINAL
ISSUE TEMP OCCUP ISSUE OCCUP
STRG SHED: SITE FINAL COMPLETE
SIGN: FTG FINAL
FENCE: SITE FINAL
MISC INSP:
NOTES: Very poor prockmanting
6 MM
INSPECTOR INITIALS: