

SEWER INSPECTION

No. 488 Napoleon, Ohio Date 10 26 19 71

Received of Alden Lash

Dollars

Charge for tapping permit to supply sewer service to lot No. \_\_\_\_\_

Addition \_\_\_\_\_

Street No. 1006 W. Washington

Sewer Size \_\_\_\_\_ inch Cost No charge

Size and Kind of Main Sewer \_\_\_\_\_

Location of Main Sewer \_\_\_\_\_

Depth of Main Sewer \_\_\_\_\_

Name LASH Size of Tap 6" VCP Date 25 Oct 71  
 Street \_\_\_\_\_ Size and Kind of Sewer \_\_\_\_\_  
 Old No. \_\_\_\_\_ Location of Sewer \_\_\_\_\_  
 New No. \_\_\_\_\_ Depth of Sewer \_\_\_\_\_  
 Crossover 6" VCP Distance to Curb Stop \_\_\_\_\_

Remarks TRENCH COVERED WHEN INSPECTION MADE House line is crooked  
going TO TAP House line BREAKS 12' EAST AFTER PASSING SW  
COR OF HOUSE AT ABOUT A 45° X WITH COR & TAP

