



WEST WASHINGTON STREET

217

OK X

X OK

ABANDONED + FILLED CISTERN

219

X OK

223

6-20-12  
INVESTIGATION OF  
ILLEGAL DOWNSPOUT  
CONNECTIONS AT  
217 W. WASHINGTON ST.  
INSPECTED BY: MARTY  
CROSSLAND

DROPPED DYE IN DOWNSPOUT  
CONNECTED UNDERGROUND  
SANITARY CLEANOUT SHOWED  
NO SIGNS OF DYE. IT IS  
ASSUMED THE CONNECTION  
WAS TO AN ABANDONED  
CISTERN AT THE REAR  
OF #217. LEACHING  
INTO SOIL FROM THERE.  
CONNECTION IS  
PERMITTED AT THIS  
LOCATION ONLY.

SCANNED