

9-9-81

ROOF DRAIN OF CHURCH GOES INTO A TILE TO MIDDLE OF WEST YARD, TURNS NORTH AND TRAVELS UNDER SIDEWALK THROUGH CURB, DUMPS ONTO STREET. THIS IS AN UNACCEPTABLE DRAINAGE PROCEDURE PUT IN BY THE CHURCH.

