

P E R M I T

CITY OF NAPOLEON  
255 W. RIVERVIEW AVE  
NAPOLEON, OHIO 43545

DIVISION OF BUILDING & ZONING  
PH (419) 592-4010  
FAX (419) 599-8393

PERMIT NO: 1693

DATE ISSUED: 06-24-03

ISSUED BY: BND

JOB LOCATION: 839 WELSTED ST

EST. COST: 3700.00

LOT #:

SUBDIVISION NAME:

OWNER: FRANZ, CHRIS  
ADDRESS: 839 WELSTED ST  
CSZ: NAPOLEON, OH 43545  
PHONE: 419-599-1630

AGENT: GREGO INC. DBA INTER  
ADDRESS: 532 E HAWTHORNE ST  
CSZ: FORT WAYNE, IN 46806  
PHONE: 260-744-4297

USE TYPE - RESIDENTIAL:

OTHER:

ZONING INFORMATION

DIST: LOT DIM: AREA: FYRD: SYRD: RYRD:  
MAX HT: # PKG SPACES: # LOADING SP: MAX LOT COV:

BOARD OF ZONING APPEALS:

WORK TYPE - NEW: REPLMNT: ADD'N: ALTER: REMODEL:

WORK INFORMATION

SIZE - LGTH: WIDTH: STORIES: LIVING AREA SF:  
GARAGE AREA SF: HEIGHT: BLDG VOL DEMO PERMIT:

WORK DESCRIPTION  
WATERPROOFING


FEE DESCRIPTION	PAID DATE	FEE AMOUNT DUE
BUILDING PERMIT		45.00

TOTAL FEES DUE 45.00

6-24-03

DATE

APPLICANT SIGNATURE



CITY OF NAPOLEON INSPECTION FORM

PERMIT #: 1693

DATE ISSUED: 06-24-2003

JOB LOCATION: 839 WELSTED ST

OWNER: FRANZ, CHRIS

OWNER PHONE: 419-599-1630

APPROVED

CONTRACTOR: GREGO INC. DBA INTERIOR CHANNE

CONTRACTOR PHONE: 260-744-4297

WORK DESCRIPTION: WATERPROOFING

PLUMBING: UNDGR \_\_\_\_\_ RGHIN \_\_\_\_\_ FINAL \_\_\_\_\_

SEWER INSP 7-2-03

MECHANICAL: UNDGR \_\_\_\_\_ RGHIN \_\_\_\_\_ FINAL \_\_\_\_\_

FURNACE REPLC \_\_\_\_\_ AIR COND \_\_\_\_\_

ELECTRICAL: UNDGR \_\_\_\_\_ RGHIN \_\_\_\_\_ FINAL \_\_\_\_\_

SERV UPGR \_\_\_\_\_

BUILDING: SITE \_\_\_\_\_ FTG \_\_\_\_\_ FNDDT \_\_\_\_\_

STRUC \_\_\_\_\_ ROOF \_\_\_\_\_ EXT \_\_\_\_\_

VENT \_\_\_\_\_ ACCES \_\_\_\_\_ EGRS \_\_\_\_\_

SMKDT \_\_\_\_\_ FINAL \_\_\_\_\_

ISSUE TEMP OCCUP \_\_\_\_\_ ISSUE OCCUP \_\_\_\_\_

STRG SHED: SITE \_\_\_\_\_ FINAL \_\_\_\_\_

SIGN: FTG \_\_\_\_\_ FINAL \_\_\_\_\_

FENCE: SITE \_\_\_\_\_ FINAL \_\_\_\_\_

MISC INSP: water proofing system / 7-2-03

NOTES: after basement water proofing system was installed, pos. sewer backed up. contractor was called back and the NW corner floor was re-applied and it was discovered that the main house sewer was cut off and plugged. contractor made repairs and reconnected pipe ends using pvc + ferro coupling. Cleanout tee installed in corner.

INSPECTOR INITIALS: BTL

Mrs. Eberly  
Wested


4'

Aug 11-1971

839

Yes

Topped in to new Sewer Aug 11-1971



ST

ST