

# City of Napoleon

## BACKFLOW PREVENTION ASSEMBLY TEST RESULTS

Property Address: 1000 Westmoreland Zip: 43345  
 Business Name: German Mutual  
 Contact Person: Rupert Knappe Title: President  
 Phone Number: 599-3993 Date of Test: 2-1-99

### DEVICE INFORMATION

Type (circle one) **RP** DC VB RPDA DCDA  
 Manf/Model: Watts 009 MI QT Size: 2" Serial No.: 94961  
 Location of Device: Boiler room East Wall  
 Type of Test: Differential Gauge  Sight Tube

Outlet Valve	Reduced Pressure Assembly			Pressure Vacuum Breaker	
	Double Check Valve		Relief Valve	Air Inlet	Check Valve
	1st Check	2nd Check			
Holding <input type="checkbox"/> Failed <input type="checkbox"/>	DC _____ psi	DC _____ psi	Opened at _____ psi	Opened at _____ psi	Held at _____ psi
Test Results	Apparent RP <u>8.8</u> psi Actual RP <u>8.4</u> psi		Did Not Open <input type="checkbox"/>	Did Not Open <input type="checkbox"/>	Leaked <input type="checkbox"/>
Date: <u>2-1-99</u>	Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>
Repairs & Materials					
Test After Repairs	DC _____ psi	DC _____ psi	Opened At _____ psi	Opened At _____ psi	Held At _____ psi
	RP _____ psi	RP _____ psi	Did Not Open <input type="checkbox"/>	Did Not Open <input type="checkbox"/>	Leaked <input type="checkbox"/>
Date:	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>

Tester Signature: [Signature] Certification No.: #2335  
 Owner/Representative Signature: [Signature]