## City of Napoleon

## BACKFLOW PREVENTION ASSEMBLY TEST RESULTS

Property Address	1000 Wes	tmoreland			Zip: 43545
	German Mutual				
Contact Person.	RuperT 1	Knate		Title: Preside	7
Phone Number	599-399	3	Date of Test:	2-1-99	
DEVICE INFORMATION					
Type (circle one)	RP	60	VB	RPDA	DCDA
Manf/Model: Walls 009m2 Size: 3/4" Serial No.: 154313					
Location of Device Boiler room East Wall					
	Differential Gauge Sight Tube				
E65594	Reduced Pressure Assembly			Pressure Vacuum Breaker	
Valve					
Holding □	Double Check Valve		Relief Valve	Air Inlet	Check Valve
Failed	1st Check	2nd Check	1.0		
	7				
Test	DC 8'2 psi	DC 1.2 psi	Opened at	Opened at	Held at
Results			psi	psi	psi
	Apparent				
	RP psi				
	Actual		Did Not	Did Not	Leaked
	RPpsi		Open	Open	
Date: 2-1-99	Pass 2	Pass 🗷	Pass 🗆	Pass	Pass
	Failed	Failed	Failed	Failed	Failed
D : 0					
Repairs &					
Materials					
T.,, A.O.	D.C.		Opened At	Opened At	Held At
	DCpsi	DCpsi	psi	psi	psi
Repairs	DD5	nn ·	Did Not	Did Not	_
	RPpsi	RP psi	Open	Open	Leaked
Data	0				
	Pass				Pass
	Failed	Failed	Failed	Failed	Failed
Taster Signature M & 17th & 1					
Tester Signature Think Velta Certification No. #2335					
Owner/Representative Signature:					