City of Napoleon

BACKFLOW PREVENTION ASSEMBLY TEST RESULTS

Property Address 1600 West more land					Zip: 43545	
Business Name:	German n	Intual				
Contact Person: Rupert Knape						
Phone Number:	599-3993		Date of Test:	-3-00		
		DEVICE IN	FORMATION			
Type (circle one)	Mes 4000 S:	DC	VB	RPDA	DCDA	
Manf/Model: A	mes 40005:	<u>S</u>	Size: 6"	Serial No.: 40 /	V1973	
Location of Device	Boiler roo	m Eastwal				
Type of Test.	Differential Gauge	X				
Outlet	Reduced Pressure	Assembly		Pressure Vacuum Breaker		
Valve						
Holding 🕉	Double Check Valve		Relief Valve	Air Inlet	Check Valve	
Failed 🗆	1st Check	2nd Check				
				*		
Test	DC psi	DCpsi	Opened at	Opened at	Held at	
Results			2.2 psi	psi	psi	
	Apparent =			ps.	psi	
	RP 10 psi				34	
	Actual		Did Not	Did Not	Leaked	
	RP 9, 8 psi		Open	Open		
Date:	Pass 2	Pass 🕱	Pass A	Pass	Pass	
	Failed	Failed	Failed		Failed	
Repairs & Materials	Should had	e drain lin	e hooked 4			
Test After Repairs	DCpsi	DC psi	Opened At psi Did Not	Opened At psi Did Not	Held At psi	
	RPpsi	RP psi	Open	Open	Leaked	
Date:	Pass	Pass 🗌	Pass 🔲	Pass 🗆	Pass 🔲	
	Failed				Failed	
Tester Signature Robert with Certification No. 3516 Owner/Representative Signature:						