

P E R M I T

CITY OF NAPOLEON
255 W. RIVERVIEW AVE
NAPOLEON, OHIO 43545

DIVISION OF BUILDING & ZONING
PH (419) 592-4010
FAX (419) 599-8393

PERMIT NO: 97146 DATE ISSUED: 05-14-97 ISSUED BY: BND
JOB LOCATION: 1315 WOODLAWN AVE EST. COST: 1000.00

LOT #: SUBDIVISION NAME:
OWNER: WEIRICH, JANET AGENT: E H GLANZ & SON
ADDRESS: 5-025 CO RD V ADDRESS: 6 LAKEVIEW DR
CSZ: LIBERTY CENTER, OH 43532 CSZ: NAPOLEON, OH 43545
PHONE: 419-533-6998 PHONE: 419-599-4103

USE TYPE - RESIDENTIAL: OTHER:

ZONING INFORMATION

DIST: LOT DIM: AREA: FYRD: SYRD: RYRD:
MAX HT: # PKG SPACES: # LOADING SP: MAX LOT COV:

BOARD OF ZONING APPEALS:

WORK TYPE - NEW: REPLMNT: ADD'N: ALTER: REMODEL:

WORK INFORMATION

DEPTH - LGTH: WIDTH: STORIES: LIVING AREA SF:
PAGE AREA SF: HEIGHT: BLDG VOL DEMO PERMIT:

WORK DESCRIPTION
SEWER LINE REPLACEMENT

FEE DESCRIPTION	PAID DATE	FEE AMOUNT DUE
SEWER PERMIT		60.00



TOTAL FEES DUE 60.00

DATE

APPLICANT SIGNATURE

CITY OF NAPOLEON INSPECTION FORM

PERMIT #: 1207

DATE ISSUED: 07-05-2002

JOB LOCATION: 1315 WOODLAWN AVE

OWNER: MEIENBURG, MATT

OWNER PHONE: 419-592-7685

CONTRACTOR: SELF

CONTRACTOR PHONE:

WORK DESCRIPTION: REPLACING STEPS

PLUMBING: UNDGR _____ RGHIN _____ FINAL _____

SEWER INSP _____

MECHANICAL: UNDGR _____ RGHIN _____ FINAL _____

FURNACE REPLC _____ AIR COND _____

ELECTRICAL: UNDGR _____ RGHIN _____ FINAL _____

SERV UPGR _____

BUILDING: SITE _____ FTG _____ FNDDT _____

STRUC _____ ROOF _____ EXT _____

VENT _____ ACCES _____ EGRS _____

SMKDT _____ FINAL _____

ISSUE TEMP OCCUP _____ ISSUE OCCUP _____

STRG SHED: SITE _____ FINAL _____

SIGN: FTG _____ FINAL _____

FENCE: SITE _____ FINAL _____

MISC INSP: _____

NOTES: _____

INSPECTOR INITIALS: _____

CITY OF NAPOLEON INSPECTION FORM

PERMIT #: 97146

DATE ISSUED: 05-14-97

JOB LOCATION: 1315 WOODLAWN AVE

OWNER: WEIRICH, JANET

OWNER PHONE: 419-533-6998

CONTRACTOR: E H GLANZ & SON

CONTRACTOR PHONE: 419-599-4103

WORK DESCRIPTION: SEWER LINE REPLACEMENT

PLUMBING: UNDGR _____ RGHIN _____ FINAL _____

SEWER INSP 5-13-97

MECHANICAL: UNDGR _____ RGHIN _____ FINAL _____

FURNACE REPLC _____ AIR COND _____

ELECTRICAL: UNDGR _____ RGHIN _____ FINAL _____

SERV UPGR _____

BUILDING: SITE _____ FTG _____ FNDDT _____

STRUC _____ ROOF _____ EXT _____

VENT _____ ACCES _____ EGRS _____

SMKDT _____ FINAL _____

ISSUE TEMP OCCUP _____ ISSUE OCCUP _____

STRG SHED: SITE _____ FINAL _____

SIGN: FTG _____ FINAL _____

FENCE: SITE _____ FINAL _____

MISC INSP: _____

NOTES: _____

INSPECTOR INITIALS: BMD

Jerry Glanz
5-13-97

Woodtown Ave

1325 W

1317 W

1315 W

1313 W

4" c/p
@ 3.4'

Removed
Septic
Tank

Footer pile
also removed
from same

1275'

4" SDR35
PVC installed
w/ ditch machine

6" c/p
@ 4' F/L
above tap

20.5'

Down
Street
to
manhole

930

920

910

906

LYNNE