

City of Napoleon

BACKFLOW PREVENTION ASSEMBLY TEST RESULTS

Property Address: 11-600 ST. RT. 424 Zip: 43545
 Business Name: Henry Co. Hospital
 Contact Person: Don Baker Title: Plant Engineer
 Phone Number: 592-4015 EXT. 406 Date of Test: 3-31-99

DEVICE INFORMATION

Type (circle one) **RP** DC VB RPDA DCDA
 Manf/Model: Watts 909 Size: 4" Serial No.: 191887
 Location of Device: North Wall near East corner of Boiler Room
 Type of Test: Differential Gauge Sight Tube

Outlet Valve	Reduced Pressure Assembly		Pressure Vacuum Breaker		
	Double Check Valve		Relief Valve	Air Inlet	Check Valve
	1st Check	2nd Check			
Holding <input checked="" type="checkbox"/> Failed <input type="checkbox"/>					
Test Results	DC _____ psi	DC _____ psi	Opened at _____ psi	Opened at _____ psi	Held at _____ psi
Date: <u>3-31-91</u>	<u>Apparent</u> RP <u>6.0</u> psi		Did Not Open <input type="checkbox"/>	Did Not Open <input type="checkbox"/>	Leaked <input type="checkbox"/>
	<u>Actual</u> RP <u>5.8</u> psi		Pass <input checked="" type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>
Repairs & Materials					
Test After Repairs	DC _____ psi	DC _____ psi	Opened At _____ psi	Opened At _____ psi	Held At _____ psi
Date:	RP _____ psi	RP _____ psi	Did Not Open <input type="checkbox"/>	Did Not Open <input type="checkbox"/>	Leaked <input type="checkbox"/>
	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>	Pass <input type="checkbox"/> Failed <input type="checkbox"/>

Tester Signature: Daniel R Brown Certification No. 528
 Owner/Representative Signature: Jerry Ewen