## City of Napoleon

## **BACKFLOW PREVENTION ASSEMBLY TEST RESULTS**

Property Address.	5T. RT. 110	By Pump	ing station	(V-8)	Zip: 43545
		Toup			
Contact Person:	David Bartley			Title: Senior	Operator
Phone Number	512-1010 E	KT. 207	Date of Test:	7-23-97	
DEVICE INFORMATION					
Type (circle one)	RP	DC	VB	RPDA	DCDA
Manf/Model: Watts 009 M2 QT Size: 2" Serial No.: 1/4918					
Location of Device	North wall	of building			
	Differential Gauge	3			
Outlet	Reduced Pressure Assembly			Pressure Vacuum Breaker	
Valve					
Holding 🛭	Double Check Valve		Relief Valve	Air Inlet	Check Valve
Failed 🗆	1st Check	2nd Check	Sanstan.		
Test	DCpsi	DC psi	Opened at	Opened at	Held at
Results Pass			3.4 psi	psi	psi
(as)	Apparent			•	
	RP 9.6 psi				III
	Actual		Did Not	Did Not	Leaked
	RP 8.1 psi		Open	Open	
Date:	Pass X	Pass 🔀	Pass 🗶	Pass 🗆	Pass 🗆
7-23-99	Failed	Failed	Failed []	Failed	Failed
Repairs &					
Materials					
			Opened At	Opened At	Held At
Test After	DCpsi	DC psi	psi	psi	psi
Repairs			Did Not	Did Not	-
	RP psi	RP psi	Open	Open	Leaked
				-	
Date:	Pass 🗆	Pass	Pass 🗆	Pass	Pass 🗆
	Failed	Failed	Failed	Failed	Failed
		0 1			
Tester Signature. Lanul & Brown Certification No. 528					
Owner/Representative Signature: David Bartley CSC					