

City of Napoleon

BACKFLOW PREVENTION ASSEMBLY TEST RESULTS

Property Address: 11-600 ST. RT. 424 Zip: 43545
 Business Name: Henry Co. Hospital
 Contact Person: Jerry Erven Title: Plant Supervisor
 Phone Number: 592-4015 Date of Test: 8-1-00

DEVICE INFORMATION

Type (circle one) RP DC **VB** RPDA DCDA
 Manf/Model: 800 m4 Watts Size: 2" Serial No.: 008843
 Location of Device: N.W. Corner outside on concrete pad
 Type of Test: Differential Gauge Sight Tube

Outlet Valve	Reduced Pressure Assembly		Pressure Vacuum Breaker		
	Double Check Valve		Relief Valve	Air Inlet	Check Valve
Holding <input checked="" type="checkbox"/>	1st Check	2nd Check			
Failed <input type="checkbox"/>					
Test Results PASS	DC _____ psi	DC _____ psi	Opened at _____ psi	Opened at <u>2.6</u> psi	Held at <u>2.2</u> psi
	<u>Apparent</u> RP _____ psi		Did Not Open <input type="checkbox"/>	Did Not Open <input type="checkbox"/>	Leaked <input type="checkbox"/>
	<u>Actual</u> RP _____ psi		Pass <input type="checkbox"/>	Pass <input checked="" type="checkbox"/>	Pass <input checked="" type="checkbox"/>
Date: 8-1-00	Failed <input type="checkbox"/>	Failed <input type="checkbox"/>	Failed <input type="checkbox"/>	Failed <input type="checkbox"/>	Failed <input type="checkbox"/>
Repairs & Materials					
Test After Repairs	DC _____ psi	DC _____ psi	Opened At _____ psi	Opened At _____ psi	Held At _____ psi
	RP _____ psi	RP _____ psi	Did Not Open <input type="checkbox"/>	Did Not Open <input type="checkbox"/>	Leaked <input type="checkbox"/>
Date:	Pass <input type="checkbox"/>	Pass <input type="checkbox"/>	Pass <input type="checkbox"/>	Pass <input type="checkbox"/>	Pass <input type="checkbox"/>
	Failed <input type="checkbox"/>	Failed <input type="checkbox"/>	Failed <input type="checkbox"/>	Failed <input type="checkbox"/>	Failed <input type="checkbox"/>

Tester Signature: Daniel R. Ben Certification No. 528
 Owner/Representative Signature: Vern Mize