

=== Line Inspection Report ===

08MAR01 01:38PM

Darrs Cleaning Inc.
Clyde,OH

<800> 541-DARR 3277

--- LOCATION HEADER ---

CUSTOMER...:Napoleon

LOCATION... :Cambridge

START MH :565 Cambridg

END MANHOLE:Appian

TAPE BEG/EN:32:44/45:21

----- LINE DATA -----

PIPE TYPE...:ADS N12

SURFACE :roadside

INSP LENGTH:375 ft

SEWER TYPE...:storm

SEWER SIZE...:15in

REPORT NO. :4

OPERATOR...:Roger Darr

FLOW.....:with

DIRECTION...:east

Record: 001

0038.6F TAP RIGHT

Record: 002

0152.7F TAP LEFT

Record: 003

0188.2F TAP RIGHT

Record: 004

0229.0F TAP LEFT

Record: 005

0267.9F

Record: 006

0273.8F

Record: 007

0281.2F

Record: 008

0318.8F

Record: 009

0374.5F

begin heavier amount of mud

manhole,veers right

clean pipe

begin mud again

mh at Apian,tap right, flow left